Exova 2395 Speakman Dr. Mississauga Ontario Canada L5K 1B3 T: +1 (905) 822-4111 F: +1 (905) 823-1446 E: sales@exova.com W: www.exova.com



Testing. Advising. Assuring.

FALL IMPACT EVALUATION OF 62.8" x 94.9" DOME SKYLIGHT "6496 FPS-FF" For: ARTISTIC SKYLIGHT DOMES LTD.

Report to:	Artistic Skylight Domes Ltd. 255 Regina Rd. Woodbridge, ON L4L 8M3
Attention: E-mail: Telephone:	Mr. Nenzio Ferrazzo nenzio.ferrazzo@artisticskylight.com 416-747-7233
Report No.:	16-06-M0200-2 RV1 3 Pages, 2 Appendix
Proposal No.:	16-006-406643
Date:	August 31, 2016

1.0 INTRODUCTION

At the request of Artistic Skylight Domes Ltd. Exova was retained to evaluate a 1595 mm x 2410 mm (62.8" x 94.9") skylight, identified as "6496 FPS-FF", for fall impact test as outlined in Exova Proposal Number 16-006-406643.

Upon receipt, the specimen was assigned the following Exova Specimen No.: 16-06-M0200-2.

The following drawings and documents in appendix B were as provided by the client and verified by Exova:

- Cross Section assembly configuration
- Bill of materials
- Die Drawings
- Technical Data Sheet

2.0 SAMPLE DESCRIPTION

Product Type: Interior rigid PVC thermal break frame with Exterior Aluminum retaining

frame and Aluminum curb frame.

Designation/model: 6496 FPS-FF

Size: 1595 mm x 2410 mm (62.8" x 94.9")

Glazing Type: Double sealed Polycarbonate dome, 3 mm (0.118") thick clear interior

and exterior dome, sealed together with 6.35 mm (0.25") Polyshim tape and

Structural Silicone.

Glazing Method: Interior dome sealed to the interior rigid PVC frame with Structural Slicone,

exterior dome sealed to the exterior aluminum frame with 3.18 mm (0.125")

Polyshim glazing type.

Installation: Exterior Aluminum retaining frame, with welded corners, fastened to the

exterior aluminum curb frame with #8 x ½" screws at 203 mm (8.0") c/c, aluminum curb frame fastened to the wood buck with #10 x 2" fasteners at

254 mm (10.0") c/c.

Weatherstrip: One row of bulb, interior rigid PVC frame at the interior dome.

One row of fin, interior rigid PVC frame at the exterior aluminum curb frame.

Hardware: None

3.0 TEST METHOD & PROCEDURE

The Building Performance Centre at Exova was to test a 1595 mm x 2410 mm (62.8" x 94.9") dome skylight in accordance with manufacturer test procedure. Observe and report visual permanent deformation and breakage at 250 lb load drop into the mid-span of dome at a specified hieght.

Test Equipment:

The following calibrated equipment was used during testing:

Measuring Tape: MII B14472Load Cell: MII B05823

4.0 OBSERVATION

Height (ft)	Load (lbs)	Energy (ft/lbs)	Observation	Photograph (Appendix A)
3	250	750	No Damage	1
3.875	250	968.75	No Damage	
4	250	1000	 Permanent deglazing at the mid-span between the sealed unit and aluminum retaining frame. Permanent deglazing at the corner between the sealed unit and aluminum retaining frame. Weight did not pass through the opening 	2-3
5	250	1250	N/A	
6	250	1500	N/A	
7	250	1750	N/A	

5.0 REPORT REVISION SUMMARY

Revision No: Date:

Original 2016-August-31 RV1 2016-September- 08

Description of Revisions:

Report issued Report revised to:

- Update contact name and email address.
- Modified description to add Structural Silicone to the glazing method and to include Aluminum curb frame.

Reported by:

Reported & Reviewed by:

Haya Soghrati, B.Arch. Sc, (Building Science), Ext. 11227 Building Systems Fenestration Services Project Manager, Products Testing Division


Sunny Ling, C.E.T., Ext. 11412 Supervisor, Building Systems Products Testing Division

APPENDIX A

Pictures

(4 pages)

Picture 1



Picture 2 (Permanent deglazing at mid-span)



Picture 3 (Permanent deglazing at corner)



APPENDIX B

Specimen Drawings and Technical Data

(17 pages)

